




Facility Name-Field Inspection Supplemental Photo Information

This information is provided to supplement the summary walkthrough inspection of the ABC , Inc. facility conducted on 12/13/14, by Tony Kuehn, ILC. This information should be viewed as supporting information relating to specific items identified during the summary walkthrough of the facility.

<u>Comment</u>	<u>Photo</u>
<p>Bench Grinder in work area needs to have the tongue guard adjusted. The upper guard (Tongue) needs to be adjusted to be within ¼ inch of the abrasive wheel.</p> <p>29 CFR 1910.215(a)(4) Abrasive Wheel Machinery - Work Rests</p> <p>Item ID: 1 Assigned to: _____, on _____ (date) To be completed by _____. Date completed: _____.</p>	
<p>Flammable storage cabinet in the parts room has a non-functional closure on the door. The cabinet should be of the self-closing type to meet MN Fire Codes and 29 CFR 1910.106 (e) (2) (ii). This is an outstanding item from previous inspections. The door latch needs to be repaired</p> <p>Item ID: 2 Assigned to: _____, on _____ (date) To be completed by _____. Date completed: _____.</p>	
<p>.</p> <p>Item ID: 3 Assigned to: _____, on _____ (date) To be completed by _____. Date completed: _____.</p>	

-END OF PHOTO INSPECTION REPORT-

This report is intended to assist in the evaluation and determination of risks and risk exposures at the above named client. It is, however, not comprehensive. Hazard and risk conditions not within our scope of work or not observed or noted during our visits are not implied to be risk free. Further, there may exist risk conditions that were not observed during our visit. Our reports are for assistance only and are not conclusive. No liability is assumed by reason of this report or the assessment on which it is based, as it is only advisory in nature and the final decisions must be made by the client.